

Turn On Phone HotSpot

Turn On GPS Isolator

Turn On Computer

Connect Phone -----→



Open AGOPENGPS

Open AgIO-----→

Start Screen. Click on the
Dark screen to continue.

Don't Close AgIO

Open/close field




Turn on AB curve

Turn on Ab line

Swap AB line

Turns coverage on



To clear Coverage

Spanner and Screwdriver





To shut down, turnoff

Coverage and hit the x,

Exit AgIO, Shutdown

Computer and turn off isolator





Click on ab curve until
The list comes up. You
Want the smoothed line.
Might have to steer by
Hand as the trimble line
Was different to the
Coupe line

